

OUT 61675

25X1

25X6 E C R E T 110251Z CITE [REDACTED] 0340

1667 APR 11 02 50Z

1. CAMERA B-15 WAS USED ON MISSION G 955 FLOWN ON 7 APRIL 1967.

PROCESSING WAS ACCOMPLISHED BY NAV RECON TECH SUPPCEN.

2. ORIGINAL NEGATIVE:

A. DENSITY AND RESOLUTION ARE GOOD.

B. BOTH SIDES: PLUS DENSITY OVALS ASSOCIATED WITH ROLLER CHATTER APPEAR INTERMITTENTLY ON BOTH SIDES THOUGHOUT THE MISSION. THE LAST FRAME IS 559. APPROXIMATELY THREE FRAMES WERE NOTED TO HAVE IMAGE SMEAR ASSOCIATED WITH VEHICLE MOVEMENT. OVERLAP ON THE VERTICAL FRAMES IS APPROXIMATELY 60 PERCENT AND THE CYCLING RATE IS 4.5 SECONDS. MODE 5 OF CAMERA OPERATION WAS USED THROUGHOUT. A TWO AND ONE-HALF INCHES PLUS DENSITY BAND IS RECORDED ON THE LAST FRAME DUE TO CAMERA MALFUNCTION.

3. POSITIVE:

A. PI SUITABILITY IS GOOD.

B. PRINTING AND PROCESSING ARE GOOD.

C. CLOUDS OBSCURED APPROXIMATELY 35 PERCENT OF THE MISSION.

S E C R E T

--END OF MESSAGE--

NGA review(s) completed.